


Features

- ✦ Easy to Use Software
- ✦ Digital Chart Records
- ✦ Multiple Sensor
- ✦ Custom Pin or Box Connections Upon Request



1.25" OD Pressure Transmitter		
Pressure	Temperature	Part No.
750 psi	85 °C	101631
1,500 psi		101630
3,000 psi		101629
5,000 psi		101628
10,000 psi		101627
15,000 psi		101626
20,000 psi		101625

Accessory Type	Part No.
USB Cable 25ft	100997
USB Cable 50ft	100998
USB Cable 100ft	100999
Adapter HF4 SS17-4	101636
Adapter 1/2 NPT SS17-4	101637
Adapter 3/4 NPT SS17-4	101638

Specifications		
	Pressure	Temperature
Accuracy Up To	0.022% F.S.	0.25 °C
Resolution	0.0003% F.S.	0.005 °C
Drift	< 3 psi / year	< 0.1 °C/year
Communication Method	USB	