






#### Features

-  Easy to Use Software
-  Digital Chart Records
-  Multiple Sensor
-  Custom Pin or Box Connections Upon Request



| 1.25" OD Pressure Transmitter    |             |          |
|----------------------------------|-------------|----------|
| Pressure                         | Temperature | Part No. |
| 750 psi                          | 85 °C       | 101631   |
| 1,500 psi                        |             | 101630   |
| 3,000 psi                        |             | 101629   |
| 5,000 psi                        |             | 101628   |
| 10,000 psi                       |             | 101627   |
| 15,000 psi                       |             | 101626   |
| 20,000 psi                       |             | 101625   |
| 1.25" OD Temperature Transmitter |             |          |
| Assembly Type                    | Temperature | Part No. |
| 3" Probe                         | 200 °C      | 101499   |
| 6" Probe                         |             | 101500   |

| Accessory Type         | Part No. |
|------------------------|----------|
| USB Cable 25ft         | 100997   |
| USB Cable 50ft         | 100998   |
| USB Cable 100ft        | 100999   |
| Adapter HF4 SS17-4     | 101636   |
| Adapter 1/2 NPT SS17-4 | 101637   |
| Adapter 3/4 NPT SS17-4 | 101638   |

| Specifications       |                |               |
|----------------------|----------------|---------------|
|                      | Pressure       | Temperature   |
| Accuracy Up To       | 0.03% F.S.     | 0.25 °C       |
| Resolution           | 0.0003% F.S.   | 0.005 °C      |
| Drift                | < 3 psi / year | < 0.1 °C/year |
| Communication Method | USB            |               |